

Bridge Inspection Report

02475

SH 7-10 Log 2.32

over

SOUTH FORK SALINE RIVER



Inspection Date:

Inspected By:

Inspection Type(s):

Inspector:


Structure Number: 02475

Inspection Date:

Facility Carried: SH 7-10 Log 2.32

Bridge Inspection Report

Location Map



Latitude: 34.59548

Longitude: -93.01223

Inspector:


Structure Number: 02475

Inspection Date:

Facility Carried: SH 7-10 Log 2.32

Bridge Inspection Report

Location Map



Latitude: 34.59548

Longitude: -93.01223

Inspector:


Structure Number: 02475

Inspection Date:

Facility Carried: SH 7-10 Log 2.32

Bridge Inspection Report

Location Map



Latitude: 34.59548

Longitude: -93.01223

Inspector:


Structure Number: 02475

Inspection Date:

Facility Carried: SH 7-10 Log 2.32

Bridge Inspection Report

Location Map



Latitude: 34.59548

Longitude: -93.01223

Inspector:

Structure Number: 02475

Inspection Date:

Facility Carried: SH 7-10 Log 2.32

Bridge Inspection Report

Maintenance Needs

Date Reported: 10/13/2015

Priority: C - Important

Work Code:

Deficiency Description:

Waterway opening under span 2 has 6' of gravel build up forcing channel to hit abutment 1

Work Description:

Date Repairs Completed:

Maintenance Comments:

Assigned Garland Co 06261 11-2-15

Stage: Assigned



PHOTO 1 Description Channel next to Bent 1.

Stage: Monitor



PHOTO 2 Description Gravel build up

Inspector:

Structure Number: 02475

Inspection Date:

Facility Carried: SH 7-10 Log 2.32

Bridge Inspection Report

Maintenance Needs

Date Reported: 10/13/2015

Priority: D - Routine

Work Code:

Deficiency Description:

Deck has small unsealed cracks

Work Description:

Date Repairs Completed:

Maintenance Comments:

Inspector:

Structure Number: 02475

Inspection Date:

Facility Carried: SH 7-10 Log 2.32

Bridge Inspection Report

Maintenance Needs

Date Reported: 10/03/2017

Priority: D - Routine

Work Code:

Deficiency Description:

Large tree washed up against column at Bt. 2.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Assigned Garland 06261 11/28/17

Stage: Open



PHOTO 1 Description Large tree washed up against column at Bt. 2.

Stage: Assigned



PHOTO 2 Description Large tree against columns at bent 2.

Inspector:

Structure Number: 02475

Inspection Date:

Facility Carried: SH 7-10 Log 2.32

Bridge Inspection Report

Maintenance Needs

Date Reported: 10/10/2018

Priority: D - Routine

Work Code:

Deficiency Description:

Columns 3 and 4 at bent 2 have large spall with exposed rebar with section loss.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 Description Bent 2 column 3, large spall with exposed rebar.

Stage: Open



PHOTO 2 Description Bent 2 column 4, large spall with exposed rebar.

Inspector:

Structure Number: 02475

Inspection Date:

Facility Carried: SH 7-10 Log 2.32

Bridge Inspection Report

Maintenance Needs

Date Reported: 10/10/2018

Priority: C - Important

Work Code:

Deficiency Description:

Bent 2 cap, ahead and back sides, large spalls with exposed rebar with section loss and large delaminated areas.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 Description Large spall with exposed rebar, ahead side of bent 2.

Stage: Open



PHOTO 2 Description Bent 2 backside, large spalls with exposed rebar and areas of delamination.