

Bridge Inspection Report

03259
Us-49/Sec-11/L0.25
over
Drainage Ditch



Inspection Date:

Inspected By:

Inspection Type(s):

TABLE OF CONTENTS

	PAGE NUMBER
LOCATION MAP	3
NATIONAL BRIDGE INVENTORY	8
ELEMENTS	9
PICTURES	11
SKETCHES	13
FIELD NOTES	14
NOTES OUTPUT	14
LOAD POSTING	15

Inspector:


Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Location Map



Latitude: 34.500111

Longitude: -90.602013

Inspector:


Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Location Map



Latitude: 34.500111

Longitude: -90.602013

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Location Map



Latitude: 34.500111

Longitude: -90.602013

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Location Map



Latitude: 34.500111

Longitude: -90.602013

Inspector:

Inspection Date:

Structure Number: 03259

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Executive Summary

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

National Bridge Inventory

IDENTIFICATION		INSPECTIONS	
(1) STATE CODE	056 - Arkansas	(90) INSPECTION DATE	03/28/2019
(8) STRUCTURE NUMBER	03259	(91) DESIGNATED INSPECTION FREQUENCY	24
(5) INV. ROUTE (ON/UNDER)	1 2 1 49 0	(92) CRITICAL FEATURE INSPECTION	(93) CFI DATE
(2) HIGHWAY AGENCY	01	(3) COUNTY CODE	107
(4) PLACE CODE	30360	A. FRACTURE CRITICAL DETAIL	N
(6) FEATURES INTERSECTED	Drainage Ditch	B. UNDERWATER INSPECTION	N
(7) FACILITY CARRIED	Us-49/Sec-11/L0.25	C. OTHER SPECIAL	N
(9) LOCATION	.74 Mi W Of Mississippi	CONDITION	
(11) MILEPOINT	0.250	(58) DECK	5
(12) BASE HIGHWAY NETWORK	1	(59) SUPERSTRUCTURE	5
(13A) LRS INVENTORY ROUTE	0000049110	(60) SUBSTRUCTURE	6
(13B) SUBROUTE NUMBER	00	(61) CHANNEL & CHANNEL PROTECTION	5
(16) LATITUDE	34.500111	(62) CULVERT	N
(17) LONGITUDE	-90.602013	LOAD RATING AND POSTING	
(98A) BORDER BRIDGE CODE		(31) DESIGN LOAD	5
PERCENT RESPONSIBILITY	(99) BORDER BRIDGE STRUCT	(63) METHOD USED TO DETERMINE OPERATING RATING	1
STRUCTURE TYPE AND MATERIAL		(64) OPERATING RATING	58.0
(43) STRUCTURE TYPE, MAIN		(65) METHOD USED TO DETERMINE INVENTORY RATING	1
A) KIND OF MATERIAL/DESIGN:	1 - Concrete	(66) INVENTORY RATING	35.1
B) TYPE OF DESIGN/CONSTR:	01 - Slab	(70) BRIDGE POSTING	5
(44) STRUCTURE TYPE, APPROACH SPANS		(41) STRUCTURE OPEN/POSTED/CLOSED	A
A) KIND OF MATERIAL/DESIGN:	0 - Other	APPRAISAL	
B) TYPE OF DESIGN/CONSTR:	00 - Other	(67) STRUCTURAL EVALUATION	5
(45) NUMBER OF SPANS IN MAIN	4	(68) DECK GEOMETRY	4
(46) NUMBER OF APPROACH	0	(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	N
(107) DECK STRUCTURE TYPE	1	(71) WATERWAY ADEQUACY	8
(108A) WEARING SURFACE	1	(72) APPROACH ROADWAY ALIGNMENT	7
(108B) DECK MEMBRANE	0	(36) TRAFFIC SAFETY FEATURE	
(108C) DECK PROTECTION	0	36A) BRIDGE RAILINGS:	0
AGE OF SERVICE		36B) TRANSITIONS:	0
(27) YEAR BUILT	1961	36C) APPROACH GUARDRAIL:	0
(106) YEAR RECONSTRUCTED	0000	36D) APPROACH GUARDRAIL ENDS:	0
(42) TYPE OF SERVICE	ON 1 UNDER 5	(113) SCOUR CRITICAL BRIDGES	5
(28) LANES	ON 02 UNDER 00	SUFFICIENCY RATING	47.9
(29) AVERAGE DAILY TRAFFIC	4600	(19) BYPASS DETOUR LENGTH	124
(30) YEAR OF AVERAGE DAILY TRAFFIC	2014	(100) STRAHNET HIGHWAY DESIGNATION	0
(109) AVERAGE DAILY TRUCK TRAFFIC	1	(101) PARALLEL STRUCTURE DESIGNATION	N
GEOMETRIC DATA		(102) DIRECTION OF TRAFFIC	2
(48) LENGTH OF MAX SPAN (ft.)	26	(103) TEMP STRUCTURE	
(49) STRUCTURE LENGTH (ft.)	104	(105) FEDERAL LANDS HIGHWAYS	0
(50) CURB/SIDEWALK WIDTHS (ft.)	LEFT 1.6 RIGHT 1.6	(110) DESIGNATED NATIONAL NETWORK	1
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.)	27.9	(20) TOLL	3
(52) DECK WIDTH, OUT-TO-OUT (ft.)	33.5	(21) MAINTENANCE RESPONSIBILITY	01
(32) APPROACH ROADWAY WIDTH (ft.)	41.0	(37) HISTORICAL	5
(33) BRIDGE MEDIAN	0	(34) SKEW (DEG.)	0
(35) STRUCTURE FLARED	0	(10) INV RTE, MIN VERT CLEAR (ft.)	99.99
(47) TOTAL HORIZONTAL CLEARANCE (ft.)	31.5	(54) VERTICAL UNDER CLEARANCE (ft.)	N 0
(53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.)	99.99	(55) LATERAL UNDER CLEARANCE RIGHT (ft.)	N 99.9
(54) VERTICAL UNDER CLEARANCE (ft.)	N 0	(56) MIN LATERAL UNDER CLEARANCE (ft.)	0
(55) LATERAL UNDER CLEARANCE RIGHT (ft.)	N 99.9	PROPOSED IMPROVEMENTS	
(56) MIN LATERAL UNDER CLEARANCE (ft.)	0	(75A) TYPE OF WORK PROPOSED	31
		(75B) WORK DONE BY	1
		(76) LENGTH OF STRUCTURE IMPROVEMENT (ft.)	131.0
		(94) BRIDGE IMPROVEMENT COST (\$)	0
		(95) ROADWAY IMPROVEMENT COST (\$)	306
		(96) TOTAL PROJECT COST	737
		(97) YEAR OF IMPROVEMENT COST ESTIMATE	2003
		(114) FUTURE ADT	6776
		(115) YEAR OF FUTURE ADT	2028
		NAVIGATION DATA	
		(38) NAVIGATION CONTROL	0
		(111) PIER OR ABUTMENT PROTECTION	1
		(39) NAV VERT CLEARANCE (ft.)	0
		(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE (ft.)	0
		(40) NAV HORIZONTAL CLEARANCE (ft.)	0

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
38 - Reinforced Concrete Slab	1- Ben.	3120	sq. ft.	3040	28	26	26
<p>Span #1 soffit left side at bent #2 lower corner has 2' spall with exposed rebar with 10% section loss. Span 1 soffit has hairline crack full length. Span #2 soffit left side at bent #2 lower corner has 1' spall with exposed rebar with 10% section loss. Span 2 soffit longitudinal crack full length with light efflorescence. Span 3 soffit has longitudinal crack full length. Span #4 soffit center span has longitudinal crack with efflorescence, 20' of delaminations, and 3' of exposed rebar with 5% section loss. Bent # 4 left side of slab at joint is cracked and spalled 1' on side of slab with no rebar exposed. Span 1 left lane has 6" x 1' asphalt patch at joint. Span #3 deck left lane has 2' x 3' and 3' x 5' patches. Span 4 at bent 4 left lane has 1' x 2' patched area. Span 4 at bent 4 left lane has 4" x 3' asphalt patch at joint, right lane has 1' x 2' asphalt patch at joint. Span #4 deck at bent #4 right lane has a 2' delamination. Span #4 deck has longitudinal crack down center with small areas of delaminations. Deck cracks have been epoxy sealed.</p>							
1080 - Delamination/Spall/Patched Area		48		0	28	20	0
1090 - Exposed Rebar		6		0	0	6	0
1130 - Cracking (RC and Other)		26		0	0	0	26
215 - Reinforced Concrete Abutment	1- Ben.	94	ft.	83	5	6	0
<p>Abutment #1 right wing has 2' spall with exposed rebar no section loss. Abutment #1 center has 1' of exposed rebar due to poor concrete coverage with 5% section loss. Abutment #2 has two 1' spalls near left side with exposed rebar and 5% section loss, a 3' area at top in center spalled with no exposed rebar, and a 2' delamination on left. Abutment #1 has large deep animal hole under abutment near center.</p>							
1080 - Delamination/Spall/Patched Area		5		0	3	2	0
1090 - Exposed Rebar		6		0	2	4	0
227 - Reinforced Concrete Pile	1- Ben.	15	each	13	2	0	0
<p>Bent #2 piles #3,5 have a hairline crack at top all the way around the pile. Bent 3 pile 3 has longitudinal crack at to backface.</p>							
1130 - Cracking (RC and Other)		2		0	2	0	0

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Element Inspection

234 - Reinforced Concrete Pier Cap	1- Ben.	92	ft.	82	2	8	0
<p>All interior bent caps on bottom has snap ties exposed and rusted. Bent #2 cap ahead face has two spalls one above pile #2 that is 1' at top no rebar exposed and one above pile #4 that is 2' and has exposed rebar with no section loss. Bent #3 cap back face has two spalls one on left lower corner that is 1' with exposed rebar no section loss, and one above pile #4 at bottom that is 1' with exposed rebar and 5% section loss. Bent #3 cap ahead face has a 3' area on left side at top with rebar exposed due to poor concrete coverage with 10% section loss. Bent #4 cap bottom has two 6" spalls with exposed rebar due to poor concrete coverage with 5% section loss. Bent #4 cap ahead face has a 1' spall above pile #2 with exposed rebar and 5% section loss.</p>							
1080 - Delamination/Spall/Patched Area		1		0	0	1	0
1090 - Exposed Rebar		9		0	2	7	0
301 - Pourable Joint Seal	1- Ben.	167	ft.	167	0	0	0
330 - Metal Bridge Railing	1- Ben.	208	ft.	208	0	0	0
331 - Reinforced Concrete Bridge Railing	1- Ben.	208	ft.	198	10	0	0
<p>Span #4 both sides have 10 total pieces of rebar exposed due to poor concrete coverage with no section loss.</p>							
1090 - Exposed Rebar		10		0	10	0	0

Inspector:

Inspection Date:

Structure Number: 03259

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Pictures

PHOTO 1
Description

PHOTO 1
Description

Inspector:

Inspection Date:

Structure Number: 03259

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Pictures

PHOTO 2

Description

Inspector:

Inspection Date:

Structure Number: 03259

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Sketches

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Maintenance Needs

Date Reported: 03/09/2017

Priority: C - Important

Work Code: N/A

Deficiency Description:

Abutment #1 right wing has 2' spall with exposed rebar no section loss.
Abutment #1 center has 1' of exposed rebar due to poor concrete coverage with 5% section loss.
Abutment #2 has two 1' spalls near left side with exposed rebar and 5% section loss, a 3' area at top in center spalled with no exposed rebar, and a 2' delamination on left.
Bent #2 cap ahead face has two spalls one above pile #2 that is 1' at top no rebar exposed and one above pile #4 that is 2' and has exposed rebar with no section loss.
Bent #3 cap back face has two spalls one on left lower corner that is 1' with exposed rebar no section loss, and one above pile #4 at bottom that is 1' with exposed rebar and 5% section loss.
Bent #3 cap ahead face has a 3' area on left side at top with rebar exposed due to poor concrete coverage with 10% section loss.
Bent #4 cap bottom has two 6" spalls with exposed rebar due to poor concrete coverage with 5% section loss.
Bent #4 cap ahead face has a 1' spall above pile #2 with exposed rebar and 5% section loss.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Monitor



PHOTO 1 Description

Stage: Monitor



PHOTO 2 Description

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Maintenance Needs

Stage: Monitor



PHOTO 3 Description

Stage: Monitor



PHOTO 4 Description Bent #2 cap

Stage: Open



PHOTO 4 Description Typical spall on caps wit exposed rebar.

Stage: Open



PHOTO 5 Description Bent # 2 front face over pile # 4.

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Maintenance Needs

Date Reported: 03/09/2017

Priority: C - Important

Work Code: N/A

Deficiency Description:

Span #3 deck left lane has one 2' spall, one 3' spall, and one 1' spall with no rebar exposed. Span #4 deck at bent #4 right lane has a 2' delamination. Span #4 deck has longitudinal crack down center with small areas of delaminations.

Work Description:

Date Repairs Completed: 03/28/2019

Maintenance Comments:

Spalls have been patched and deck cracks have been epoxy sealed at time of inspection.

Stage: Open



PHOTO 1 Description

Stage: Monitor



PHOTO 1 Description Span #3 deck

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Maintenance Needs

Stage: Monitor




PHOTO 2 Description Span #4 has longitudinal crack down center with small areas of delaminations.

Stage: Monitor




PHOTO 4 Description Span 4 crack has been epoxy sealed.

Stage: Monitor



PHOTO 3 Description Span 4 at bent 4 left lane patched.



PHOTO 5 Description Span 3 left lane patches.

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Maintenance Needs

Date Reported: 03/16/2015

Priority: D - Routine

Work Code: N/A

Deficiency Description:

Abutment #1 has large deep animal hole under abutment near center.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 Description Abutment # 2 left wing.

Stage: Monitor



PHOTO 1 Description Abutment #1 has large deep animal hole under abutment near center.

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Maintenance Needs

Stage: Monitor



PHOTO 2 Description Abutment 1 animal hole has been sandbagged.

Stage: Open



PHOTO 3 Description Abutment # 2 animal hole .

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Maintenance Needs

Date Reported: 03/09/2017

Priority: D - Routine

Work Code: N/A

Deficiency Description:

Dirt and debris is built up on approach shoulders making it hard for water to run off.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 Description Dirt and debris is built up on approach shoulders making it hard for water to run off.

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Maintenance Needs

Date Reported: 03/09/2017

Priority: D - Routine

Work Code: N/A

Deficiency Description:

Span #1 soffit left side at bent #2 lower corner has 2" spall with exposed rebar with 10% section loss.

Span #2 soffit left side at bent #2 lower corner has 1" spall with exposed rebar with 10% section loss.

Span #4 soffit center span has longitudinal crack with efflorescence, 20" of delaminations, and 3" of exposed rebar with 5% section loss.

Bent # 4 left side of slab at joint is cracked and spalled 1" on side of slab with no rebar exposed.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 Description Span #2 soffit left side at bent #2 lower corner has 1' spall with exposed rebar with 10% section loss.

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Maintenance Needs

Date Reported: 03/28/2019

Priority: C - Important

Work Code: N/A

Deficiency Description:

Abutment 2 right approach rail has 20'+- collision damage approximately 25' from bridge end.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 Description Abutment 2 right approach rail has 20' +- collision damage 25' from bridge end.

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Maintenance Needs

Date Reported: 03/28/2019

Priority: C - Important

Work Code: N/A

Deficiency Description:

Beaver dam across channel, left side of bridge approximately 60' from bridge.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open




PHOTO 1 Description Large beaver dam left side, approximately 60' from bridge.

Inspector:

Structure Number: 03259

Inspection Date:

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Maintenance Needs

Date Reported: 03/09/2017

Priority: C - Important

Work Code: N/A

Deficiency Description:

Trees and vegetation are growing beside and under bridge.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 Description Trees and vegetation are growing beside and under bridge and onto roadway.

Stage: Monitor



PHOTO 1 Description Trees and vegetation growing beside and under bridge.

Inspector: Davis, Joel

Inspection Date: 03/28/2019

Structure Number: 03259

Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Deck/Culvert Notes

Deck:

Span #1 soffit left side at bent #2 lower corner has 2' spall with exposed rebar with 10% section loss.

Span 1 soffit has hairline crack full length.

Span #2 soffit left side at bent #2 lower corner has 1' spall with exposed rebar with 10% section loss.

Span 2 soffit longitudinal crack full length with light efflorescence.

Span 3 soffit has longitudinal crack full length.

Span #4 soffit center span has longitudinal crack with efflorescence, 20' of delaminations, and 3' of exposed rebar with 5% section loss.

Bent # 4 left side of slab at joint is cracked and spalled 1' on side of slab with no rebar exposed.

Span 1 left lane has 6" x 1' asphalt patch at joint.

Span #3 deck left lane has 2' x 3' and 3' x 5' patches.

Span 4 at bent 4 left lane has 1' x 2' patched area.

Span 4 at bent 4 left lane has 4" x 3'

asphalt patch at joint, right lane has 1' x 2'

asphalt patch at joint.

Span #4 deck at bent #4 right lane has a 2' delamination.

Span #4 deck has longitudinal crack down center with small areas of delaminations.

Deck cracks been epoxy sealed.

Approach slabs:

Approach slabs are overlaid with asphalt.

Railing:

Span #4 both sides have 10 total pieces of rebar exposed due to poor concrete coverage with no section loss.

SuperStructure Notes

SubStructure Notes

Abutments:

Abutment #1 right wing has 2' spall with exposed rebar no section loss.

Abutment #1 center has 1' of exposed rebar due to poor concrete coverage with 5% section loss.

Abutment #2 has two 1' spalls near left side with exposed rebar and 5% section loss, a 3' area at top in center spalled with no exposed rebar, and a 2' delamination on left.

Abutment #1 has large deep animal hole under abutment near center.

Piles:

Bent #2 piles #3,5 have a hairline crack at top all the way around the pile.

Caps:

All interior bent caps on bottom has snap ties exposed and rusted.

Bent #2 cap ahead face has two spalls one above pile #2 that is 1' at top no rebar exposed and one above pile #4 that is 2' and has exposed rebar with no section loss.

Bent #3 cap back face has two spalls one on left lower corner that is 1' with exposed rebar no section loss, and one above pile #4 at bottom that is 1' with exposed rebar and 5% section loss.

Bent #3 cap ahead face has a 3' area on left side at top with rebar exposed due to poor concrete coverage with 10% section loss.

Bent #4 cap bottom has two 6" spalls with exposed rebar due to poor concrete coverage with 5% section loss.

Bent #4 cap ahead face has a 1' spall above pile #2 with exposed rebar and 5% section loss.

Inspector: Davis, Joel
Inspection Date: 03/28/2019

Structure Number: 03259
Facility Carried: Us-49/Sec-11/L0.25

Bridge Inspection Report

Load Posting

Legal Load	Calculated
CODE 4 VEHICLE (22 tons)	36 Tons
CODE 9 VEHICLE (31 tons)	42 Tons
CODE 5 VEHICLE (40 tons)	55 Tons

If calculated < legal load posting is required